OCV Control Valves
Registered to ISO 9001
Global performance. Personal touch.

Part Number: 930100 - Viton

1330 Relief Pilot

Repair Parts Kit-Viton

Part Number: 930100
For: 1330 Relief Pilot

Parts List

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		611010	2	DIAPHRAGM PLATE 'O' RING	Viton
2		611012	1	STEM 'O' RING	Viton
3		611116	1	ADAPTER 'O' RING	Viton
4		611912	1	PLUG 'O' RING	Viton
5		694102	1	DIAPHRAGM	Viton
6		310709	1	SEAT DISC	S.S. & Viton
7		685760	1	SEAL WASHER	S.S.

7400 E. 42nd Place, Tulsa, OK 74145-4744 USA • fax: (918) 622.8916 • email: sales@controlvalves.com
1.888.OCV.VALV (628.8258) • www.controlvalves.com

OCV Control Valves
Registered to ISO 9001
Global performance. Personal touch.

Part Number: 930100 - Viton

1330 Relief Pilot



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	611010	2	DIAPHRAGM PLATE 'O' RING	Viton
2	611012	1	STEM 'O' RING	Viton
3	611116	1	ADAPTER 'O' RING	Viton
4	611912	1	PLUG 'O' RING	Viton
5	694102	1	DIAPHRAGM	Viton
6	310709	1	SEAT DISC	S.S. & Viton
7	685760	1	SEAL WASHER	S.S.

7400 E. 42nd Place, Tulsa, OK 74145-4744 USA • fax: (918) 622.8916 • email: sales@controlvalves.com
1.888.OCV.VALV (628.8258) • www.controlvalves.com