


Repair Parts Kit-Buna

Part Number: 930017

For: 1380 Excess Float Pilot Kit

Parts List

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		610906	1	'O' RING	Buna-N
2		611008	1	'O' RING	Viton
3		694002	1	DIAPHRAGM	Buna-N
4		611116	1	'O' RING	Viton
5		611010	3	'O' RING	Viton
6		610910	1	'O' RING	Buna-N
7		611012	1	'O' RING	Viton
8		305728	1	SPOOL DISK	S.S./Buna-N



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	610906	1	'O' RING	Buna-N
2	611008	1	'O' RING	Viton
3	694002	1	DIAPHRAGM	Buna-N
4	611116	1	'O' RING	Viton
5	611010	3	'O' RING	Viton
6	610910	1	'O' RING	Buna-N
7	611012	1	'O' RING	Viton
8	305728	1	SPOOL DISC	S.S./Buna-N