


Repair Parts Kit-Buna
 Part Number: 920009
 For: 800 Float Pilot Repair Kit

Parts List

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		651708	2	SPRING	S.S.
2		695503	2	DISC	Viton
3		610022	2	'O' RING	Buna-N
4		611011	5	'O' RING	Viton
5		611005	3	'O' RING	Viton
6		610218	1	'O' RING	Buna-N



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	651708	2	SPRING	S.S.
2	695503	2	DISC	Viton
3	610022	2	'O' RING	Buna-N
4	611011	5	'O' RING	Viton
5	611005	3	'O' RING	Viton
6	610218	1	'O' RING	Buna-N