


Repair Parts Kit-Viton

Power Actuated 66

Part Number: 906105

For: 10" 1800 Repair Kit

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		693115	1	GASKET	Viton
2		690116	1	DIAPHRAGM	Viton
3		691505	1	SEAT DISC	Viton
4		611227	1	'O' RING	Viton
5		611218	2	'O' RING	Viton
6		611327	1	'O' RING	Viton
7		611277	1	'O' RING	Viton
8		630721	1	RETAINING RING	S.S.



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	693115	1	GASKET	Viton
2	690116	1	DIAPHRAGM	Viton
3	691505	1	SEAT DISC	Viton
4	611227	1	'O' RING	Viton
5	611218	2	'O' RING	Viton
6	611327	1	'O' RING	Viton
7	611277	1	'O' RING	Viton
8	630721	1	RETAINING RING	S.S.