


Repair Parts Kit-Buna
 Part Number: 930010
 For: 1356 Differential Pilot

Parts List

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		610906	1	'O' RING	Buna
2		611008	1	'O' RING	Viton
3		611010	2	'O' RING	Viton
4		694002	1	DIAPHRAGM	Buna-N
5		611012	1	'O' RING	Viton
6		611116	1	'O' RING	Viton
7		310703	1	SEAT DISC	S.S./Buna-N
8		685760	1	SEAL WASHER	S.S./Buna
9		610912	1	'O' RING	Buna-N



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	610906	1	'O' RING	Buna
2	611008	1	'O' RING	Viton
3	611010	2	'O' RING	Viton
4	694002	1	DIAPHRAGM	Buna-N
5	611012	1	'O' RING	Viton
6	611116	1	'O' RING	Viton
7	310703	1	SEAT DISC	S.S./Buna-N
8	685760	1	SEAL WASHER	S.S./Buna
9	610912	1	'O' RING	Buna-N