


**Repair Parts Kit-Buna**  
 Part Number: 935017  
 For: 1380 Overhaul Kit

**Parts List**

Item	Included	Part #	Quantity	Description	Material
1		694002	1	DIAPHRAGM	Buna-N
2		305728	1	SPOOL	S.S./Buna
3		314705	1	STEM	S.S.
4		620708	1	ROLL PIN	S.S.
5		610910	1	'O' RING	Buna-N
6		611010	3	'O' RING	Viton
7		611116	1	'O' RING	Viton
8		611008	1	'O' RING	Viton
9		611906	1	'O' RING	Viton
10		611012	1	'O' RING	Viton
11		314722	1	LOCKING STEM	S.S.
12		651705	1	STEM SPRING	S.S.
13		300723	1	ADJUSTING SCREW	S.S.
14		300709	1	ADJUSTING SCREW LOCKNUT	S.S.
15		630715	1	ADJUSTING SCREW 'E' RING	S.S.
16		532701	1	LOCKING STEM SCREW	S.S.
17		685720	1	LOCKING STEM WASHER	S.S.



Item	Part #	Quantity	Description	Material
1	694002	1	DIAPHRAGM	Buna-N
2	305728	1	SPOOL	S.S./Buna
3	314705	1	STEM	S.S.
4	620708	1	ROLL PIN	S.S.
5	610910	1	'O' RING	Buna-N
6	611010	3	'O' RING	Viton
7	611116	1	'O' RING	Viton
8	611008	1	'O' RING	Viton
9	611906	1	'O' RING	Viton
10	611012	1	'O' RING	Viton
11	314722	1	LOCKING STEM	S.S.
12	651705	1	STEM SPRING	S.S.
13	300723	1	ADJUSTING SCREW	S.S.
14	300709	1	ADJUSTING SCREW LOCKNUT	S.S.
15	630715	1	ADJUSTING SCREW 'E' RING	S.S.
16	532701	1	LOCKING STEM SCREW	S.S.
17	685720	1	LOCKING STEM WASHER	S.S.