


Repair Parts Kit-Viton

Part Number: 930107

For: 2420 High Pressure Reducing Pilot
 & 2400 High Pressure Relief Pilot

Parts List

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		694109	1	DIAPHRAGM	Viton
2		611011	2	'O' RING	Viton
3		611012	1	'O' RING	Viton
4		611116	1	'O' RING	Viton
5		310709	1	SEAT DISC	S.S./Viton
6		611912	1	'O' RING	Viton
7		685760	1	SEAL WASHER	S.S./Buna-N



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	694109	1	DIAPHRAGM	Viton
2	611011	2	'O' RING	Viton
3	611012	1	'O' RING	Viton
4	611116	1	'O' RING	Viton
5	310709	1	SEAT DISC	S.S./Viton
6	611912	1	'O' RING	Viton
7	685760	1	SEAL WASHER	S.S./Buna-N