


Repair Parts Kit-Buna
Power Actuated Valve with Lift Check Assembly
 Part Number: 906026
 For: 10" 3800 Repair Kit

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		693036	1	GASKET	Buna-N
2		690073	1	DIAPHRAGM	Buna-N
3		690505	1	SEAT DISC	Buna-N
4		610227	1	'O' RING	Buna-N
5		610218	1	'O' RING	Buna-N
6		610327	1	'O' RING	Buna-N
7		610277	1	'O' RING	Buna-N
8		610324	1	'O' RING	Buna-N



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	693036	1	GASKET	Buna-N
2	690073	1	DIAPHRAGM	Buna-N
3	690505	1	SEAT DISC	Buna-N
4	610227	1	'O' RING	Buna-N
5	610218	1	'O' RING	Buna-N
6	610327	1	'O' RING	Buna-N
7	610277	1	'O' RING	Buna-N
8	610324	1	'O' RING	Buna-N