


Repair Parts Kit-Buna
Power Actuated Valve with Lift Check Assembly
 Part Number: 906013
 For: 6" 6195 Repair Kit (7/8" Stem)

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		693014	1	GASKET	Buna-N
2		690043	1	DIAPHRAGM	Buna-N
3		690503	1	SEAT DISC	Buna-N
4		610220	1	'O' RING	Buna-N
5		610016	1	'O' RING	Buna-N
6		610218	1	'O' RING	Buna-N
7		610259	1	'O' RING	Buna-N
8		630724	1	RETAINING RING	S.S.
9		610212	1	'O' RING	Buna-N



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	693014	1	GASKET	Buna-N
2	690043	1	DIAPHRAGM	Buna-N
3	690503	1	SEAT DISC	Buna-N
4	610220	1	'O' RING	Buna-N
5	610016	1	'O' RING	Buna-N
6	610218	1	'O' RING	Buna-N
7	610259	1	'O' RING	Buna-N
8	630724	1	RETAINING RING	S.S.
9	610212	1	'O' RING	Buna-N