


**Repair Parts Kit-Buna
 Power Actuated Valve with Lift Check Assembly**

Part Number: 906085

For: 8" 3200 Repair Kit

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		693084	1	GASKET	Buna-N
2		690085	1	DIAPHRAGM	Buna-N
3		690584	1	SEAT DISC	Buna-N
4		610227	1	'O' RING	Buna-N
5		611214	2	'O' RING	Viton
6		611327	1	'O' RING	Viton
7		610268	1	'O' RING	Buna-N
8		610133	1	'O' RING	Buna-N
9		610320	1	'O' RING	Buna-N



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	693084	1	GASKET	Buna-N
2	690085	1	DIAPHRAGM	Buna-N
3	690584	1	SEAT DISC	Buna-N
4	610227	1	'O' RING	Buna-N
5	611214	2	'O' RING	Viton
6	611327	1	'O' RING	Viton
7	610268	1	'O' RING	Buna-N
8	610133	1	'O' RING	Buna-N
9	610320	1	'O' RING	Buna-N