


**Repair Parts Kit-Viton
 Power Actuated 66
 Part Number: 906105
 For: 10" 1800 Repair Kit**

| ITEM | INCLUDED | PART# | QTY | DESCRIPTION | MATERIAL |
|------|----------|--------|-----|----------------|----------|
| 1 | | 693115 | 1 | GASKET | Viton |
| 2 | | 690116 | 1 | DIAPHRAGM | Viton |
| 3 | | 691505 | 1 | SEAT DISC | Viton |
| 4 | | 611227 | 1 | 'O' RING | Viton |
| 5 | | 611218 | 2 | 'O' RING | Viton |
| 6 | | 611327 | 1 | 'O' RING | Viton |
| 7 | | 611277 | 1 | 'O' RING | Viton |
| 8 | | 630721 | 1 | RETAINING RING | S.S. |



| ITEM | PART# | QTY | DESCRIPTION | MATERIAL |
|------|--------|-----|----------------|----------|
| 1 | 693115 | 1 | GASKET | Viton |
| 2 | 690116 | 1 | DIAPHRAGM | Viton |
| 3 | 691505 | 1 | SEAT DISC | Viton |
| 4 | 611227 | 1 | 'O' RING | Viton |
| 5 | 611218 | 2 | 'O' RING | Viton |
| 6 | 611327 | 1 | 'O' RING | Viton |
| 7 | 611277 | 1 | 'O' RING | Viton |
| 8 | 630721 | 1 | RETAINING RING | S.S. |