


Repair Parts Kit-Buna
Power Actuated Valve with Lift Check Assembly
 Part Number: 906009
 For: 2.5" Repair Kit

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		693027	1	GASKET	Buna-N
2		690056	1	DIAPHRAGM	Buna-N
3		690510	1	SEAT DISC	Buna-N
4		610024	1	'O' RING	Buna-N
5		611014	1	'O' RING	Viton
6		611116	1	'O' RING	Viton
7		610152	1	'O' RING	Buna-N
8		611112	1	'O' RING	Viton



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	693027	1	GASKET	Buna-N
2	690056	1	DIAPHRAGM	Buna-N
3	690510	1	SEAT DISC	Buna-N
4	610024	1	'O' RING	Buna-N
5	611014	1	'O' RING	Viton
6	611116	1	'O' RING	Viton
7	610152	1	'O' RING	Buna-N
8	611112	1	'O' RING	Viton