


Repair Parts Kit-Buna
Power Actuated Valve with Lift Check Assembly
 Part Number: 965231
 For: 2" 2265 Basic Valve Repair Kit

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		2053	1	DIAPHRAGM	Nylon & Buna-N
2		2054	1	SEAT DISC	Buna



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	2053	1	DIAPHRAGM	Nylon & Buna-N
2	2054	1	SEAT DISC	Buna