


Repair Parts Kit-Buna
Power Actuated Valve with Lift Check Assembly
 Part Number: 906019
 For: 3" 2700 Repair Kit

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		693010	1	GASKET	Buna-N
2		690012	1	DIAPHRAGM	Buna-N
3		690501	1	SEAT DISC	Buna-N
4		610020	1	'O' RING	Buna-N
5		611014	1	'O' RING	Viton
6		611113	1	'O' RING	Viton
7		610240 or 610044	1	'O' RING	Buna-N
8		610114	1	'O' RING	Buna-N



ITEM	PART#	QTY	DESCRIPTION	MATERIAL
1	693010	1	GASKET	Buna-N
2	690012	1	DIAPHRAGM	Buna-N
3	690501	1	SEAT DISC	Buna-N
4	610020	1	'O' RING	Buna-N
5	611014	1	'O' RING	Viton
6	611113	1	'O' RING	Viton
7	610240 or 610044	1	'O' RING	Buna-N
8	610114	1	'O' RING	Buna-N