

Repair Parts Kit-Buna
Power Actuated Valve with Lift Check Assembly
 Part Number: 904023
 For: 6" 6153 Repair Kit (5/8" Stem)

ITEM	INCLUDED	PART#	QTY	DESCRIPTION	MATERIAL
1		693014	1	GASKET	Buna-N
2		690014	1	DIAPHRAGM	Buna-N
3		690503	1	SEAT DISC	Buna-N
4		610218	1	'O' RING	Buna-N
5		610016	1	'O' RING	Buna-N
6		610214	1	'O' RING	Buna-N
7		610259	1	'O' RING	Buna-N
8		630704	1	RETAINING RING	S.S.
9		610208	1	'O' RING	Buna-N

6"
Power-Actuated